ASBESTOS ASSES

H-K Building / Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/27/89 Inspector: CURT BAXTER Building Number: 37
Building Name: PARTS

SEATTLE, WASHINGTON 98134

Building Type: GARAGE Year Constructed: 1949

******* AREA NUMBER: 01	AREA DESCRIPTION: 1st Floor-Ceiling AREA			AREA AVE	AVERAGE % ASBESTOS: 0%				******			
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	YTITHAUP	UNITS OF MEASURE	PIPE	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
throughout	02-356624 02-356625 02-356626	0% 0% 0%	acoustical tile	OMG	280 s	q.ft.						
AREA COMMENTS							AREA # 01	TOT	AL	\$(\$0	\$0

******* AREA NUMBER: 02 AREA DESCRIPTION: 1st Floor				AREA AVERAGE	******		
	LOCATION OF THE MATERIAL	SAMPLE NUMBER ASB MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE EXP ID POT PL	REMOVAL COSTS	REPLACEMENT TOTAL COSTS COSTS
	center of room-between storage racks	01-356621 10% mjp on non-suspect pipe co 01-356622 10% 01-356623 8%	ver OMA	1 6 in. O.D.	DR 25 111 25 111 25 111) \$23 \$6

AREA COMMENTS

AREA # 02 TOTAL \$39 \$23 \$62

The material is in good condition with minor contact and water damage. The material is approximately 8' from the floor. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

BUILDING # 37	TOTAL	\$39	\$23	\$62
---------------	-------	------	------	------

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 73

06/09/89